



Make	MERCEDES-BENZ
Type	ANTOS 2536
Kind	Truck
Specification	Frigo
Matriculation year	2014
Chassisnumber	WDB9630201L855401
Mileage	655,861 km
Technical condition	★★★★★

Price

€ 32900



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

Equipment

Chassis

Number of axles	3
Configuration	6x2
Twin tires	✓
Loading Capacity	12,570 kg
Own weight	13,430 kg
Gross vehicle weight	26,000 kg
Total fuel capacity	600 litre
Suspension type	air suspension

Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Drivers position	Left hand drive
Color	white

Drivetrain

Engine make	Mercedes
Engine capacity	265 Kw (355 Pk)
Euro	6
Distribution type	Cogwheels
Gearbox kind	Automatic
Speed limiter	✓
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Boxmaterial	isolated
-------------	----------

Refrigeration unit

Enginemade frigo-unit	Thermoking
Enginetype frigo-unit	T-1000R
Enginetype frigo-unit	fuel and electrical
Isolated box	✓
Type of cooling	Cooling and freezing
Day/night cooling	day and night cooling

Taillift

Taillift	✓
Tail-lift kind	sliderlift
Tail-lift capacity	1,500 kg
Tail-lift make	Dhollandia
Tail-lift material	steel and aluminium
Tail-lift size	170x240
Tail-lift voltage	24

Remarks

CHEREAU WITH BACK DOORS / THERMO KING TS 1000-R / FOLDABLE TAILLIFT

Tyres/Wheels

Sparewheel	✓
Spare tire profile	9 mm

Inspection report

Chassis

- Tacho ★★★★★
- Dashboard display codes ★★★★★
- Electrical ★★★★★

Cabin

- Internal ★★★★★
- External ★★★★★
- Steering column ★★★★★
- Suspension ★★★★★
- Chassis ★★★★★
- Brakes ★★★★★

Drivetrain

- Engine, general ★★★★★
- Cooling system ★★★★★
- Fuel system ★★★★★
- Exhaust system ★★★★★
- Greasing system ★★★★★
- Gearbox ★★★★★
- Clutch ★★★★★
- Drivetrain ★★★★★

Superstructure

- Superstructure ★★★★★
- Internal condition ★★★★★
- External condition ★★★★★

Refrigeration unit

- Systems ★★★★★


Taillift

- Controls ★★☆☆☆
- System ★★★☆☆

Tyres/Wheels

- Tyres ★★★★★

- ★★★★★★ Very good state
- ★★★★★ Good state
- ★★★★☆ Reasonable state
- ★★★☆☆ Moderate state
- ★☆☆☆☆ Does not meet requirements



Tires and axles

