

SCHMITZ SKO 24 FP COOL 40 CARRIER VECTOR 15

KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES



Itemno 298662
Kind Semi-trailer
Specification Frigo
Matriculation year 2013 / 01
Mileage

Chassisnumber
WSM00000005094686

Technical condition

Remarks
BLOEMENBREED / INSIDE WIDTH 250
(A15)

Price €20950



Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Loading Capacity 33,390 kg
Own weight 8,610 kg
Gross vehicle weight 42,000 kg
Chassis type Incomplete chassis
Chassis material steel
Kingpin size 2 inch
Wheelbase 891 cm
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS
EBS

Superstructure

Matr. year superstructure 2,013
Inner box length 1,340 cm
Inner box width 250 cm
Inner box height 2,265 cm
Netto height 263 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit vector1550
Enginetype frigo-unit fuel and electrical
Working hours electric 1,974
Working hours diesel 18,504
Wall thickness 45 mm

Axle

Axle make SCHMITZ

Remarks

Remarks BLOEMENBREED / INSIDE
WIDTH 250 CM

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



Tire size: 385/65R22,5
air suspension
Disc brakes



Tire size: 385/65R22,5
air suspension
Disc brakes



Tire size: 385/65R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements