

## DAF XF 105.460 SSC INTARDER 493TKM



Itemno 300553  
Kind Truck  
Specification BDF System  
Matriculation year 2013 / 10  
Mileage 492,839 km

Chassisnumber  
XLRAE47MS0G005463

Technical condition

Remarks

( A15 )

**Price € 14950**



# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Own weight 8,520 kg  
Gross vehicle weight 18,600 kg  
Total fuel capacity 1,040 litre  
2nd fuel tank √  
Trailer coupling √  
Kingpin size Special  
Diff. locks 1  
Wheelbase 540 cm  
Suspension type air suspension

### Taillift

Taillift √  
Tail-lift kind normal  
Tail-lift capacity 1,500 kg  
Tail-lift make Zepro  
Tail-lift material steel  
Tail-lift size 200x245

### Cabin

Cabin type Super Space Cab  
Cruise control √  
Tacho √  
Digital tachograph √  
Airconditioning √  
Parking Airco √  
Parking heater √  
Color Multicolored

### Drivetrain

Engine capacity 340 Kw (462 Hp)  
Euro 5  
Gearbox kind AS-tronic  
Number of Gears 12  
Add. break system √  
Retarder make Intarder  
Power steering √  
ABS √  
ASR √

### Superstructure

Twistlocks 1x20  
Load bed height 86 cm  
System length 80 cm

### Contact information



info@kleyn.com


Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands

IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U

KvK 11013784  
BTW/VAT NL004676841B01

## Inspection report

### Chassis

|                         |          |
|-------------------------|----------|
| Tacho                   | ●●●●●●●● |
| Dashboard display codes | ●●●●●●●● |
| Electrical              | ●●●●●●●● |

### Cabin

|                 |          |
|-----------------|----------|
| Internal        | ●●●●●●●● |
| External        | ●●●●●●●● |
| Steering column | ●●●●●●●● |
| Suspension      | ●●●●●●●● |
| Chassis         | ●●●●●●●● |
| Brakes          | ●●●●●●●● |

### Drivetrain

|                 |          |
|-----------------|----------|
| Engine, general | ●●●●●●●● |
| Cooling system  | ●●●●●●●● |
| Fuel system     | ●●●●●●●● |
| Exhaust system  | ●●●●●●●● |
| Greasing system | ●●●●●●●● |
| Gearbox         | ●●●●●●●● |
| Clutch          | ●●●●●●●● |
| Drivetrain      | ●●●●●●●● |

### Superstructure

|                    |          |
|--------------------|----------|
| External condition | ●●●●●●●● |
|--------------------|----------|

### Taillift

|          |          |
|----------|----------|
| Controls | ●●●●●●●● |
| System   | ●●●●●●●● |

### Tyres/Wheels

Tyres



1



Tire size: 315/70R22,5  
spring suspension  
Disc brakes  
Steering-axle, Mechanical

2



Tire size: 295/60R22,5  
air suspension  
Disc brakes

## Contact information



info@kleyn.com  
Tel: +31 183 668 222

## Legenda for inspection report

|          |                            |
|----------|----------------------------|
| ●●●●●●●● | Very good state            |
| ●●●●●●●● | Good state                 |
| ●●●●●●●● | Reasonable state           |
| ●●●●●●●● | Moderate state             |
| ●●●●●●●● | Does not meet requirements |