

## MERCEDES-BENZ ACTROS 1851



Itemno 301381  
Kind Tractor unit  
Specification  
Matriculation year 2018 / 09  
Mileage 898,942 km

**Chassisnumber**  
WDF9634031B998907

Technical condition

**Remarks**  
2019 chass nr,tipperhydr  
( A15 )

**Price € 29900**

# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands

IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U

KvK 11013784  
BTW/VAT NL004676841B01

## Equipment

### Chassis

|                      |                     |
|----------------------|---------------------|
| Number of axles      | 2                   |
| Configuration        | 4x2                 |
| Own weight           | 7,852 kg            |
| Gross vehicle weight | 18,000 kg           |
| Total fuel capacity  | 390 litre           |
| Fifth wheel height   | 122 cm              |
| Diff. locks          | 1                   |
| Wheelbase            | 380 cm              |
| Aluminium rims       | ✓                   |
| Suspension type      | full air suspension |

### Cabin

|                    |           |
|--------------------|-----------|
| Cabin type         | Megaspace |
| Cruise control     | ✓         |
| Tacho              | ✓         |
| Digital tachograph | ✓         |
| Airconditioning    | ✓         |
| Parking Airco      | ✓         |
| Parking heater     | ✓         |
| Color              | Silver    |

### Drivetrain

|                        |                 |
|------------------------|-----------------|
| Engine make            | Mercedes        |
| Engine capacity        | 375 Kw (510 Hp) |
| Euro                   | 6               |
| Gearbox kind           | Telligent       |
| Number of Gears        | 12              |
| Power steering         | ✓               |
| ABS                    | ✓               |
| ASR                    | ✓               |
| Hydraulic installation | ✓               |
| PTO                    | ✓               |

### Superstructure

|      |   |
|------|---|
| Pump | ✓ |
|------|---|

### Remarks

|         |                          |
|---------|--------------------------|
| Remarks | 2019 chass nr,tipperhydr |
|---------|--------------------------|

### Contact information




info@kleyn.com  
Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



# KLEYN TRUCKS

KLEYN GROUP

KLEYN VANS

KLEYN TRAILERS

KLEYN SERVICES

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands  
  
IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U  
  
KvK 11013784  
BTW/VAT NL004676841B01

Inspection report

Chassis

|                         |                                                                    |
|-------------------------|--------------------------------------------------------------------|
| Tacho                   | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Dashboard display codes | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Electrical              | <div><div></div><div></div><div></div><div></div><div></div></div> |

Cabin

|                 |                                                                    |
|-----------------|--------------------------------------------------------------------|
| Internal        | <div><div></div><div></div><div></div><div></div><div></div></div> |
| External        | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Steering column | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Suspension      | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Chassis         | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Brakes          | <div><div></div><div></div><div></div><div></div><div></div></div> |

Drivetrain

|                 |                                                                    |
|-----------------|--------------------------------------------------------------------|
| Engine, general | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Cooling system  | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Fuel system     | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Exhaust system  | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Greasing system | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Gearbox         | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Clutch          | <div><div></div><div></div><div></div><div></div><div></div></div> |
| Drivetrain      | <div><div></div><div></div><div></div><div></div><div></div></div> |

Tyres/Wheels

|       |                                                                    |
|-------|--------------------------------------------------------------------|
| Tyres | <div><div></div><div></div><div></div><div></div><div></div></div> |
|-------|--------------------------------------------------------------------|

Tires and axles



Tire size: 385/65R22,5  
air suspension  
Disc brakes  
Steering-axle, Mechanical



Tire size: 315/80R22,5  
air suspension  
Disc brakes

Contact information



info@kleyn.com  
Tel: +31 183 668 222

Legenda for inspection report

|                                                                    |                            |
|--------------------------------------------------------------------|----------------------------|
| <div><div></div><div></div><div></div><div></div><div></div></div> | Very good state            |
| <div><div></div><div></div><div></div><div></div><div></div></div> | Good state                 |
| <div><div></div><div></div><div></div><div></div><div></div></div> | Reasonable state           |
| <div><div></div><div></div><div></div><div></div><div></div></div> | Moderate state             |
| <div><div></div><div></div><div></div><div></div><div></div></div> | Does not meet requirements |