

VOLVO FH 500 XL X-LOW MEGA 2XTANK



Itemno 306249
Kind Tractor unit
Specification
Matriculation year 2017 / 05
Mileage 719,434 km

Chassisnumber
YV2RT40A5HB820904

Technical condition

Remarks

(A15)

Price €31900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 7,963 kg
Gross vehicle weight 18,000 kg
Total fuel capacity 830 litre
2nd fuel tank
Fifth wheel height 100 cm
Diff. locks 1
Wheelbase 370 cm
Aluminium rims
Suspension type full air suspension

Cabin

Cruise control
Tacho
Digital tachograph
Airconditioning
Parking Airco
Parking heater
Color Multicolored

Drivetrain

Engine capacity 375 Kw (510 Hp)
Euro 6
Gearbox kind I-Shift
Number of Gears 12
Power steering
ABS
ASR

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



1
Tire size: 315/60R22,5
air suspension
Disc brakes
Steering-axle, Mechanical



2
Tire size: 295/55R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●●	Good state
●●●●●	Reasonable state
●●●●●	Moderate state
●●●●●	Does not meet requirements