

SCHMITZ SKI 24 SL 8.2 ISOLATED DAMAGED



298846

06 / 2014

WSK00000001280518



TIPPING CYLINDER BROKEN, ISOLATION
) A15 (

11900 €



Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

3
6,960
39,000

inch 2 Kingpin

) 0(
√
√

2,014

850
228
150
29
3

SCHMITZ

,TIPPING CYLINDER BROKEN
ISOLATION LEFT HAND SIDE
BROKEN



info@kleyn.com
Tel: +31 183 668 222



Kleyn

Trucks



KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U


KvK 11013784
BTW/VAT NL004676841B01



/



info@kleyn.com
Tel: +31 183 668 222



/