



Make	IVECO
Type	150E25 EUROCARGO
Kind	Truck
Specification	Frigo
Matriculation year	2016
Chassisnumber	ZCFA71LJ802654669
Mileage	312,589 km
Technical condition	★★★★★

Price

€ 34900



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Own weight	9,380 kg
Gross vehicle weight	15,000 kg
Total fuel capacity	100 litre
Diff. locks	1
Suspension type	air suspension

### Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Drivers position	Left hand drive
Color	white

### Drivetrain

Engine capacity	185 Kw (248 Pk)
Euro	6
Gearbox kind	Manual
Number of Gears	6
Clutch Pedal	✓
Power steering	✓
ABS	✓
ASR	✓

### Superstructure

Matr. year superstructure	2,016
---------------------------	-------

### Refrigeration unit

Enginetype frigo-unit	Carrier
-----------------------	---------

### Refrigeration unit

Enginetype frigo-unit	Supra 750Mt
Enginetype frigo-unit	fuel and electrical
Working hours diesel	1,590
Isolated box	✓
Day/night cooling	day and night cooling
Additional evaporator	✓

### Taillift

Taillift	✓
Tail-lift kind	normal
Tail-lift capacity	1,500 kg
Tail-lift make	Dautel
Tail-lift material	aluminium
Tail-lift size	255x230

### Remarks

SCHMITZ FRIGO BOX / DAUTEL TAILLIFT/ CARRIER SUPRA 750 MULTI TEMP /

### Tyres/Wheels

Sparewheel	✓
Spare tire profile	12 mm

## Inspection report

### Chassis

Tacho	★★★★★
Dashboard display codes	★★★★★
Electrical	★★★★★

### Cabin

Internal	★★★★★
External	★★★★★
Steering column	★★★★★
Suspension	★★★★★
Chassis	★★★★★
Brakes	★★★★★

### Drivetrain

Engine, general	★★★★★
Cooling system	★★★★★
Fuel system	★★★★★
Exhaust system	★★★★★
Greasing system	★★★★★
Gearbox	★★★★★
Clutch	★★★★★
Drivetrain	★★★★★

### Superstructure

Internal condition	★★★★★
External condition	★★★★★

### Refrigeration unit

Systems	★★★★★
---------	-------


### Taillift

Controls	★★★★★
System	★★★★★

### Tyres/Wheels

Tyres	★★★★★
-------	-------

★★★★★★	Very good state
★★★★★	Good state
★★★★	Reasonable state
★★★	Moderate state
★★	Does not meet requirements



## Tires and axles

