



| | |
|---------------------|-------------------|
| Make | SCANIA |
| Type | P230 |
| Kind | Truck |
| Specification | Frigo |
| Matriculation year | 2007 |
| Chassisnumber | VLUP4X20009124003 |
| Mileage | 808,852 km |
| Technical condition | ★★★★★ |



More information about this vehicle?

Contact me

Kleyn

+31 183 668 222

info@kleyn.com

Equipment

Chassis

| | |
|----------------------|----------------|
| Number of axles | 2 |
| Configuration | 4x2 |
| Twin tires | ✓ |
| Loading Capacity | 12,300 kg |
| Own weight | 6,700 kg |
| Gross vehicle weight | 19,000 kg |
| Total fuel capacity | 300 litre |
| Diff. locks | 1 |
| Suspension type | air suspension |

Cabin

| | |
|--------------------|-----------------|
| Cabin type | Short cabin |
| Cruise control | ✓ |
| Tacho | ✓ |
| Digital tachograph | ✓ |
| Airconditioning | ✓ |
| Drivers position | Left hand drive |
| Color | white |

Drivetrain

| | |
|-----------------|-----------------|
| Engine make | Scania |
| Engine capacity | 169 Kw (227 Pk) |
| Fuel type | diesel |
| Euro | 4 |
| Gearbox kind | Manual |
| Number of Gears | 8 |
| Clutch Pedal | ✓ |
| Power steering | ✓ |
| ABS | ✓ |
| ASR | ✓ |

Chairs

| | |
|-----------------|---|
| Number of seats | 2 |
|-----------------|---|

Refrigeration unit

| | |
|-----------------------|-----------------------|
| Enginemake frigo-unit | Carrier |
| Enginetype frigo-unit | Supra 550 |
| Enginetype frigo-unit | fuel and electrical |
| Working hours diesel | 6,309 |
| ATP-condition | FEC 10 - 2013 |
| Isolated box | ✓ |
| Wall thickness | 60 mm |
| Type of cooling | Cooling and freezing |
| Day/night cooling | day and night cooling |

Taillift

| | |
|--------------------|-----------|
| Taillift | ✓ |
| Tail-lift kind | normal |
| Tail-lift capacity | 1,500 kg |
| Tail-lift make | Dhollanda |
| Tail-lift material | aluminium |
| Tail-lift size | 200 x 250 |
| Tail-lift voltage | 24 |

Inspection report

Chassis

- Tacho ★★★★★
- Dashboard display codes ★★★★★
- Electrical ★★★★★

Cabin

- Internal ★★★★
- External ★★★★
- Steering column ★★★★★
- Suspension ★★★★★
- Chassis ★★★★★
- Brakes ★★★★★

Drivetrain

- Engine, general ★★★★★
- Cooling system ★★★★★
- Fuel system ★★★★★
- Exhaust system ★★★★★
- Greasing system ★★★★★
- Gearbox ★★★★★
- Clutch ★★★★★
- Drivetrain ★★★★★

Superstructure

- Internal condition ★★★★
- External condition ★★★★

Refrigeration unit

- Systems ★★★★★

Taillift

- Controls ★★★★
- System ★★★★

Tyres/Wheels

- Tyres ★★★★

- ★★★★★★ Very good state
- ★★★★★ Good state
- ★★★★ Reasonable state
- ★★★ Moderate state
- ★ Does not meet requirements



Tires and axles

