

M.A.N. 19.322 F90 MANUAL



Itemno 287451
Kind Tractor unit
Specification
Matriculation year 1993 / 01
Mileage 1,582,753 km

Chassisnumber
WMAF02W547M166195

Technical condition

Remarks

(A15)

Price € 5900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 7,000 kg
Gross vehicle weight 19,000 kg
Total fuel capacity 400 litre
Fifth wheel height 118 cm
Wheelbase 345 cm
Central lubrication ✓
Suspension type air suspension

Cabin

Cabin type Sleeping cabin
Cruise control ✓
Tacho ✓
Color Yellow

Drivetrain

Engine capacity (0 Hp)
Euro 1
Distribution type Cogwheels
Gearbox kind Manual
Number of Gears 12
Clutch Pedal ✓
Power steering ✓

Tyres/Wheels

Sparewheel ✓
Spare tire profile 5 mm

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 295/80R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●●	Good state
●●●●●	Reasonable state
●●●●●	Moderate state
●●●●●	Does not meet requirements