

VOLVO FM 13.500 6X2 BOOGIE NL-TRUCK



Itemno 292351
Kind Truck
Specification Cable system
Matriculation year 2010 / 09
Mileage 1,252,435 km

Chassisnumber
YV2JG30C7AB566051

Technical condition

Remarks

(A15)

Price € 12900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x2
Loading Capacity	16,625 kg
Own weight	11,375 kg
Gross vehicle weight	28,000 kg
Total fuel capacity	610 litre
Trailer coupling	✓
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	23,952 kg
Kingpin size	Special
Diff. locks	1
Wheelbase	480 cm
Suspension type	air suspension

Cabin

Cabin type	Sleeping cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Multicolored

Drivetrain

Engine make	Volvo
Engine capacity	375 Kw (510 Hp)
Fuel type	diesel
Euro	5
Gearbox kind	I-Shift
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓
Hydraulic installation	✓
PTO	✓

Superstructure

Material superstructure	steel
Systemlength	640 cm
Pump	✓

Chairs

Number of seats	2
-----------------	---

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleytn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Superstructure

Hydraulics	●●●●●●●●
Superstructure	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



1
Tire size: 385/65R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



2
Tire size: 315/80R22,5
air suspension
Disc brakes



3
Tire size: 315/80R22,5
Lift axle
air suspension
Disc brakes

Contact information



info@kleytn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements