

RENDERS VÉDÉCAR FRIGO CARRIER MAXIMA



Itemno 294734
Kind Semi-trailer
Specification Frigo
Matriculation year 2002 / 03
Mileage

Chassisnumber
YA5B304A239B55458

Technical condition

Remarks
TAILLIFT BROKEN / LAADKLEP DEFECT
(A15)

Price € 5950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 8,930 kg
Gross vehicle weight 39,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Suspension type full air suspension

Remarks

Remarks
TAILLIFT BROKEN /
LAADKLEP DEFECT

Tyres/Wheels

Sparewheel ✓

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,002
Inner box length 1,340 cm
Inner box width 250 cm
Inner box height 275 cm
Netto height 274 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit maxima1200
Enginetype frigo-unit fuel and electrical
Working hours electric 2,437
Working hours diesel 8,982
Wall thickness 45 mm

Axle

Axle make BPW

Taillift

Taillift ✓
Tail-lift kind sliderlift
Tail-lift capacity 1,502 kg
Tail-lift make d hollandia
Tail-lift material steel and aluminium

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/55R22,5
air suspension
Disc brakes



2

Tire size: 385/55R22,5
air suspension
Disc brakes



3

Tire size: 385/55R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements