

DAF XF 460 SPACECAB MEGA



Itemno 296732
 Kind Tractor unit
 Specification
 Matriculation year 2015 / 07
 Mileage 1,157,587 km
Chassisnumber
 XLRTEH4300G038058

Technical condition
Remarks

(A15)

Price € 12950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	10,979 kg
Own weight	8,021 kg
Gross vehicle weight	19,000 kg
Total fuel capacity	845 litre
Fifth wheel height	99 cm
Diff. locks	1
Wheelbase	380 cm
Suspension type	air suspension

Cabin

Cabin type	Space Cab
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Multicolored
Metallic	✓

Drivetrain

Engine capacity	338 Kw (459 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	AS-tronic
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓
PTO	✓

Chairs

Number of seats	2
-----------------	---

Contact information



info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



1 Tire size: 305/70R22,5
spring suspension
Disc brakes



2 Tire size: 315/60R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●●	Good state
●●●●●	Reasonable state
●●●●●	Moderate state
●●●●●	Does not meet requirements