

VOLVO FH 13.420 8X2 LIVE ANIMALS



Itemno 296832
 Kind Truck
 Specification Cattle transport
 Matriculation year 2010 / 07
 Mileage 787,592 km
Chassisnumber
 YV2AG10C4AA695178
 Technical condition
Remarks
 NOT FOR SALE TO DENMARK
 (A15)

Price € 12950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 4
 Configuration 8x2
 Own weight 20,400 kg
 Gross vehicle weight 29,500 kg
 Total fuel capacity 300 litre
 Diff. locks 1
 Wheelbase 660 cm
 Suspension type full air suspension

Cabin

Cabin type Short cabin
 Cruise control ✓
 Tacho ✓
 Digital tachograph ✓
 Color white
 Reversing camera ✓

Drivetrain

Engine make Volvo
 Engine capacity 315 Kw (428 Hp)
 Euro 5
 Gearbox kind I-Shift
 Number of Gears 12
 Power steering ✓
 ABS ✓
 ASR ✓
 PTO ✓

Superstructure

Inner box length 986 cm
 Inner box width 248 cm
 Inner box height 280 cm
 Load bed height 90 cm
 Netto height 273 cm
 Pump ✓

Taillift

Taillift ✓
 Tail-lift kind normal
 Tail-lift make Zepro
 Tail-lift material stainless steel
 Tail-lift size 273 x 248
 Tail-lift voltage 24

Remarks

Remarks NOT FOR SALE TO DENMARK

Contact information




info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles

1



Tire size: 385/55R22,5

air suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/60R22,5

Lift axle

air suspension

Disc brakes

Steering-axle

3



Tire size: 315/60R22,5

air suspension

Disc brakes

4



Tire size: 315/60R22,5

Lift axle

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements