

DAF XF 440 SPACECAB SPOILERS



Itemno 298109
Kind Tractor unit
Specification
Matriculation year 2017 / 02
Mileage 720,679 km

Chassisnumber
XLRTEH4100G145313

Technical condition

Remarks

(A15)

Price € 14900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 7,912 kg
Gross vehicle weight 19,500 kg
Total fuel capacity 1,245 litre
2nd fuel tank √
Fifth wheel height 116 cm
Diff. locks 1
Wheelbase 380 cm
Suspension type air suspension

Cabin

Cabin type Space Cab
Cruise control √
Tacho √
Digital tachograph √
Airconditioning √
Parking heater √
Color Multicolored

Drivetrain

Engine make Paccar
Engine capacity 320 Kw (435 Hp)
Euro 6
Gearbox kind AS-tronic
Number of Gears 12
Power steering √
ABS √
ASR √

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



1 Tire size: 315/80R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



2 Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements