

SCHMITZ SKO 24 DOPPELSTOCK MULTI TEMP



Itemno 298196
Kind Semi-trailer
Specification Frigo
Matriculation year 2016 / 07
Mileage

Chassisnumber
WSM00000005161676

Technical condition

Remarks

(A15)

Price € 18900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 8,720 kg
Gross vehicle weight 39,000 kg
Chassis type Incomplete chassis
Chassis material steel
Kingpin size 2 inch
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,016
Inner box length 1,340 cm
Inner box width 250 cm
Inner box height 270 cm
Netto height 246 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit vector1950
Enginetype frigo-unit fuel and electrical
Working hours electric 215
Working hours diesel 5,100
Wall thickness 40 mm
Additional evaporator ✓

Axle

Axle make SCHMITZ

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/55R22,5
air suspension
Disc brakes



2

Tire size: 385/55R22,5
air suspension
Disc brakes



3

Tire size: 385/55R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements