

DAF XF 460 SPACECAB MEGA LOWDEC



Itemno 298776
 Kind Tractor unit
 Specification
 Matriculation year 2016 / 05
 Mileage 583,355 km
Chassisnumber
 XLRTEH4300G107686

Technical condition 
Remarks

(A15)

Price € 14900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Own weight 8,175 kg
 Gross vehicle weight 19,500 kg
 Total fuel capacity 700 litre
 Fifth wheel height 98 cm
 Diff. locks 1
 Wheelbase 380 cm
 Suspension type air suspension

Cabin

Cabin type Sleeping cabin
 Cruise control ✓
 Tacho ✓
 Digital tachograph ✓
 Airconditioning ✓
 Parking heater ✓
 Color white

Drivetrain

Engine make Paccar
 Engine capacity 340 Kw (462 Hp)
 Euro 6
 Gearbox kind AS-tronic
 Number of Gears 12
 Power steering ✓
 ABS ✓
 ASR ✓

Contact information



info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



Tire size: 385/55R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/60R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements