

MERCEDES-BENZ ACTROS 1848 LS NR RET. ALCO



Itemno 299102
Kind Tractor unit
Specification
Matriculation year 2017 / 07
Mileage 723,338 km

Chassisnumber
WDB96340610181415

Technical condition

Remarks
BigSpace,standklima,durabright,low liner
(A15)

Price € 29900

KLEYN TRUCKS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP VANS TRAILERS SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	8,135 kg
Gross vehicle weight	18,000 kg
Total fuel capacity	990 litre
2nd fuel tank	✓
Fifth wheel height	95 cm
Diff. locks	1
Wheelbase	370 cm
Aluminium rims	✓
Suspension type	full air suspension

Cabin

Cabin type	High roof
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking Airco	✓
Parking heater	✓
Color	Silver
Metallic	✓

Drivetrain

Engine capacity	350 Kw (476 Hp)
Euro	6
Gearbox kind	Telligent
Number of Gears	12
Add. break system	✓
Retarder make	Voith
Power steering	✓
ABS	✓
ASR	✓

Remarks

Remarks BigSpace,standklima,durabright
,low liner

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 355/50R22,5
air suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 295/55R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements