

VOLVO FM 12.420 6X2 SINGLE BOOGIE



Itemno 299378
Kind Tractor unit
Specification
Matriculation year 2005 / 11
Mileage 939,059 km

Chassisnumber
YV2JN60C66A612408

Technical condition

Remarks

(A15)

Price € 7950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x2
Gross vehicle weight	26,000 kg
Total fuel capacity	405 litre
Fifth wheel height	116 cm
fifth-wheel	Slide
Diff. locks	1
Wheelbase	305 cm
Aluminium rims	✓
Suspension type	air suspension

Cabin

Cabin type	Globetrotter
Cruise control	✓
Tacho	✓
Airconditioning	✓
Color	Red

Drivetrain

Engine make	Volvo
Engine capacity	309 Kw (420 Hp)
Euro	3
Gearbox kind	I-Shift
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓
Hydraulic installation	✓
PTO	✓

Superstructure

Pump	✓
------	---

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

KleyN Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	---

Tires and axles



Tire size: 315/80R22,5
Lift axle
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes



Tire size: 385/55R22,5
Lift axle
air suspension
Disc brakes

Contact information



info@kleyN.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements