

DAF XF 460 SPACECAB MEGA



Itemno 299444
 Kind Tractor unit
 Specification
 Matriculation year 2015 / 06
 Mileage 1,267,775 km
Chassisnumber
 XLRTEH4300G038053

Technical condition
Remarks

(A15)

Price € 12950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	10,976 kg
Own weight	8,024 kg
Gross vehicle weight	19,000 kg
Total fuel capacity	800 litre
Fifth wheel height	97 cm
Diff. locks	1
Wheelbase	380 cm
Suspension type	air suspension

Cabin

Cabin type	Space Cab
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Multicolored

Drivetrain

Engine make	Paccar
Engine capacity	340 Kw (462 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	AS-tronic
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Chairs

Number of seats	2
-----------------	---

Contact information




info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP

KLEYN VANS

KLEYN TRAILERS

KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 295/60R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 295/60R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements