

VOLVO FH 750 6X2 FRIGO COMBI



Itemno 299527
Kind Truck
Specification Frigo
Matriculation year 2015 / 01
Mileage 666,632 km

Chassisnumber
YV2R0P0C5FA771640

Technical condition

Remarks

(A15)

Price € 46900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x2
Twin tires	✓
Own weight	14,675 kg
Gross vehicle weight	28,000 kg
Total fuel capacity	810 litre
Trailer coupling	✓
Kingpin size	Special
Diff. locks	1
Wheelbase	460 cm
Suspension type	full air suspension

Cabin

Cabin type	Globetrotter XL
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Blue
Metallic	✓

Drivetrain

Engine capacity	552 Kw (750 Hp)
Euro	6
Gearbox kind	I-Shift
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	674 cm
Inner box width	251 cm
Inner box height	275 cm
Load bed height	130 cm
Netto height	254 cm

Refrigeration unit

Enginemake frigo-unit	Carrier
Enginetype frigo-unit	fuel and electrical
Wall thickness	45 mm
Type of cooling	Cooling
Day/night cooling	day and night cooling
Additional evaporator	✓

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



1



Tire size: 385/65R22,5

air suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/70R22,5

air suspension

Disc brakes

3



Tire size: 315/60R22,5

Lift axle

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements