

MERCEDES-BENZ ACTROS 1843 LS ALCOA PTO RE



Itemno 300504
Kind Tractor unit
Specification
Matriculation year 2017 / 03
Mileage 656,866 km

Chassisnumber
WDB96340310129066

Technical condition

Remarks

(A15)

Price € 18900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	7,223 kg
Gross vehicle weight	18,000 kg
Total fuel capacity	390 litre
Fifth wheel height	119 cm
Diff. locks	1
Wheelbase	370 cm
Aluminium rims	✓
Suspension type	air suspension

Cabin

Cabin type	High roof
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking Airco	✓
Parking heater	✓
Color	Blue

Drivetrain

Engine make	Mercedes
Engine capacity	315 Kw (428 Hp)
Euro	6
Gearbox kind	Telligent
Number of Gears	12
Add. break system	✓
Retarder make	Voith
Power steering	✓
ABS	✓
ASR	✓
PTO	✓

Superstructure

Bulkcompressor	✓
----------------	---

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Tyres/Wheels

Tyres

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements