

VAN HOOL MULTI HIGH CUBE MB DISC BRAKES



Itemno 300637
 Kind Semi-trailer
 Specification Container transport
 Matriculation year 2005 / 01
 Mileage
Chassisnumber
 YE13B0070AA406391
 Technical condition 
Remarks

(A15)

Price € 3450



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
 Loading Capacity 32,660 kg
 Own weight 5,340 kg
 Gross vehicle weight 38,000 kg
 Chassis type Complete chassis
 Chassis material steel
 Kingpin size 2 inch
 Wheelbase 870 cm
 Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
 ABS ✓
 EBS ✓

Superstructure

Matr. year superstructure 2,007
 Container sizes 1x20/2x20/1x30/1x40

Lowloader

Extendable chassis Rear

Axle

Axle make MERCEDES-BENZ

Contact information




info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5

Lift axle

air suspension

Disc brakes



2

Tire size: 385/65R22,5

air suspension

Disc brakes



3

Tire size: 385/65R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements