

## RENAULT D 220 11.9T AIRCO TAILLIFT



Itemno 300668  
Kind Truck  
Specification Closed box  
Matriculation year 2018 / 07  
Mileage 407,879 km

**Chassisnumber**  
VF640J562JB009334

Technical condition

**Remarks**

( A15 )

**Price € 39950**



# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Twin tires ✓  
Loading Capacity 5,135 kg  
Own weight 6,855 kg  
Gross vehicle weight 11,990 kg  
Total fuel capacity 200 litre  
Wheelbase 530 cm  
Suspension type air suspension

### Cabin

Cabin type Short cabin  
Cruise control ✓  
Tacho ✓  
Digital tachograph ✓  
Airconditioning ✓  
Color white

### Drivetrain

Engine capacity 162 Kw (220 Hp)  
Fuel type diesel  
Euro 6  
Gearbox kind Optidriver  
Number of Gears 8  
Power steering ✓  
ABS ✓  
ASR ✓

### Superstructure

Inner box length 720 cm  
Inner box width 249 cm  
Inner box height 238 cm  
Load bed height 105 cm  
Netto height 232 cm

### Chairs

Number of seats 2

### Taillift

Taillift ✓  
Tail-lift kind normal  
Tail-lift capacity 1,500 kg  
Tail-lift make D Hollandia  
Tail-lift material aluminium  
Tail-lift size 250x170

### Contact information



info@kleyn.com


Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Inspection report

### Chassis

Tacho



Dashboard display codes



Electrical



### Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



### Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



### Superstructure

Internal condition



External condition



### Taillift

Controls



System



### Tyres/Wheels

Tyres



1



Tire size: 245/70R19,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 245/70R19,5

air suspension

Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 222

### Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements