

DAF LF 230 12T MANUAL AIRCO



Itemno 300697
Kind Truck
Specification Closed box
Matriculation year 2018 / 02
Mileage 200,119 km

Chassisnumber
XLRAEL1700L471764

Technical condition

Remarks

(A15)

Price € 33900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 5,975 kg
Own weight 6,015 kg
Gross vehicle weight 11,990 kg
Total fuel capacity 300 litre
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 13,200 kg
Wheelbase 500 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color white

Drivetrain

Engine make Paccar
Engine capacity 172 Kw (234 Hp)
Fuel type diesel
Euro 6
Gearbox kind Manual
Number of Gears 6
Clutch Pedal ✓
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 727 cm
Inner box width 247 cm
Inner box height 243 cm
Load bed height 98 cm
Netto height 236 cm

Chairs

Number of seats 2

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 1,500 kg
Tail-lift make Dautel
Tail-lift material aluminium
Tail-lift size 180 x 252

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 245/70R17,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 245/70R17,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements