

SCHWARZMUELLER S1 BIG VOLUME LIFT AXLE



Itemno 301013
Kind Semi-trailer
Specification Moving floor
Matriculation year 2018 / 12
Mileage

Chassisnumber
VAVJS1339JH409298

Technical condition 

Remarks

(A15)

Price € 31900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Loading Capacity 28,520 kg
Own weight 7,480 kg
Gross vehicle weight 36,000 kg
Chassis type Incomplete chassis
Chassis material aluminium
Kingpin size 2 inch
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,018
Material superstructure aluminium
Inner box length 1,355 cm
Inner box width 247 cm
Inner box height 283 cm
Netto height 276 cm

Axle

Axle make SAF

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 445/45R19,5

Lift axle

air suspension

Disc brakes



2

Tire size: 445/45R19,5

air suspension

Disc brakes



3

Tire size: 445/45R19,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements