# SCANIA R580 6X2 HYVA











| | |
|---|---|
| Itemno | 301250 |
| Kind | Truck |
| Specification | Hooklift |
| Matriculation year | 2017 / 07 |
| Mileage | 906,027 km |
| **Chassisnumber** | |
| YS2R6X20002136499 | |
| Technical condition | |
| **Remarks** | |
| ( A15 ) | |

**Price € 67900**

KLEYN TRUCKS

KLEYN GROUP | KLEYN VANS | KLEYN TRAILERS | KLEYN SERVICES


Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01


## Equipment

### Chassis

| | |
|---|---|
| Number of axles | 3 |
| Configuration | 6x2 |
| Loading Capacity | 14,569 kg |
| Own weight | 12,431 kg |
| Gross vehicle weight | 27,000 kg |
| Total fuel capacity | 600 litre |
| Trailer coupling | √ |
| Unbraked towing capacity | 750 kg |
| Braked towing capacity, center axle | 24,000 kg |
| Kingpin size | 40 DIN |
| Diff. locks | 1 |
| Wheelbase | 610 cm |
| Aluminium rims | √ |
| Suspension type | full air suspension |

### Cabin

| | |
|---|---|
| Cruise control | √ |
| Tacho | √ |
| Digital tachograph | √ |
| Airconditioning | √ |
| Parking heater | √ |
| Color | white |

### Drivetrain

| | |
|---|---|
| Engine capacity | 427 Kw (580 Hp) |
| Fuel type | diesel |
| Euro | 6 |
| Gearbox kind | Opti-cruise |
| Number of Gears | 12 |
| Add. break system | √ |
| Retarder make | Scania |
| Power steering | √ |
| ABS | √ |
| ASR | √ |
| Hydraulic installation | √ |
| PTO | √ |

### Superstructure

| | |
|---|---|
| Load bed heigth | 122 cm |
| Systemlength | 570 cm |
| Pump | √ |
| Hook-lift height | 144 |

### Chairs

| | |
|---|---|
| Number of seats | 2 |

**Contact information**





info@kleyn.com
Tel: +31 183 668 222


**Certified and professional**

Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions




Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

## Inspection report

### Chassis

| | |
|---|---|
| Tacho | ●●●●○ |
| Dashboard display codes | ●●●●○ |
| Electrical | ●●●●○ |

### Cabin

| | |
|---|---|
| Internal | ●●●○○ |
| External | ●●●○○ |
| Steering column | ●●●●○ |
| Suspension | ●●●●○ |
| Chassis | ●●●●○ |
| Brakes | ●●●●○ |

### Drivetrain

| | |
|---|---|
| Engine, general | ●●●●○ |
| Cooling system | ●●●●○ |
| Fuel system | ●●●●○ |
| Exhaust system | ●●●●○ |
| Greasing system | ●●●●○ |
| Gearbox | ●●●●○ |
| Clutch | ●●●●○ |
| Drivetrain | ●●●●○ |

### Superstructure

| | |
|---|---|
| Hydraulics | ●●●●○ |
| External condition | ●●●●○ |

### Tyres/Wheels

| | |
|---|---|
| Tyres | ●●●●○ |

## Tires and axles

**1**




Tire size: 385/65R22,5
air suspension
Disc brakes
Steering-axle, Mechanical

**2**




Tire size: 315/80R22,5
air suspension
Disc brakes

**3**




Tire size: 315/80R22,5
Lift axle
air suspension
Disc brakes

**Contact information**




info@kleyn.com
Tel: +31 183 668 222

**Legenda for inspection report**

| | |
|---|---|
| ●●●●● | Very good state |
| ●●●●○ | Good state |
| ●●●○○ | Reasonable state |
| ●●○○○ | Moderate state |
| ●○○○○ | Does not meet requirements |