DAF CF 85.410 SPACECAB CARIER LIFT











Itemno	301428
Kind	Truck
Specification	Frigo
Matriculation year	2013 / 01
Mileage	989,495 km

Chassisnumber
XLRAE85MC0E958675

Technical condition

Remarks

(A15)

Price € 19950

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	6,995 kg
Own weight	11,605 kg
Gross vehicle weight	18,600 kg
Total fuel capacity	850 litre
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	24,000 kg
Diff. locks	1
Wheelbase	570 cm
Suspension type	air suspension

Cabin

Cabin type	Super Space Cab
Cruise control	√
Tacho	√
Digital tachograph	√
Airconditioning	√
Color	white

Drivetrain

Engine make	Paccar
Engine capacity	301 Kw (409 Hp)
Fuel type	diesel
Euro	5
Gearbox kind	Automatic
Number of Gears	12
Power steering	√
ABS	√

Superstructure

Inner box length	774 cm
Inner box width	248 cm
Inner box heigth	268 cm
Load bed heigth	123 cm
Netto height	267 cm

Chairs

Number of seats	2

Refrigiration unit

Enginemake frigo-unit	Carrier
Enginetype frigo-unit	SUPRA 750 Nordic
Enginetype frigo-unit	fuel and electrical
Working hours diesel	1,627
Isolated box	√
Wall thickness	45 mm
Type of cooling	Freezing
Day/night cooling	day and night cooling

Taillift

Taillift	√
Tail-lift kind	sliderlift
Tail-lift capacity	1,500 kg
Tail-lift make	Dhollandia
Tail-lift material	aluminium
Tail-lift size	171 x 240

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional

Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP | KLEYN VANS | KLEYN TRAILERS | KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●○
Dashboard display codes	●●●●○
Electrical	●●●●○

Cabin

Internal	●●●○○
External	●●●○○
Steering column	●●●●○
Suspension	●●●●○
Chassis	●●●●○
Brakes	●●●●○

Drivetrain

Engine, general	●●●●○
Cooling system	●●●●○
Fuel system	●●●●○
Exhaust system	●●●●○
Greasing system	●●●●○
Gearbox	●●●●○
Clutch	●●●●○
Drivetrain	●●●●○

Superstructure

Internal condition	●●●○○
External condition	●●○○○

Refrigiration unit

Systems	●●●○○

Taillift

Controls	●●●●○
System	●●●○○

Tyres/Wheels

Tyres	●●●○○

Tires and axles

1



Tire size: 315/60R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical

2



Tire size: 315/60R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●○	Good state
●●●○○	Reasonable state
●●○○○	Moderate state
●○○○○	Does not meet requirements