

M.A.N. 18.400 TGS LX TS PTO ALCOA'S



Itemno 301577
Kind Tractor unit
Specification
Matriculation year 2016 / 11
Mileage 598,733 km

Chassisnumber
WMA08SZZ1HP083000

Technical condition

Remarks

(A15)

Price € 17950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 11,525 kg
Own weight 7,075 kg
Gross vehicle weight 18,600 kg
Total fuel capacity 530 litre
Fifth wheel height 116 cm
Diff. locks 1
Wheelbase 390 cm
Aluminium rims ✓
Suspension type air suspension

Cabin

Cabin type Sleeping cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Parking heater ✓
Color Multicolored

Drivetrain

Engine capacity 294 Kw (400 Hp)
Fuel type diesel
Euro 6
Gearbox kind Automatic
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Chairs

Number of seats 2

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements