

M.A.N. 26.350 TGA 6X2 MANUAL 539 TKM



Itemno 301695
Kind Truck
Specification Chassis Cabin
Matriculation year 2006 / 04
Mileage 538,712 km

Chassisnumber
WMAH18ZZX6W063518

Technical condition

Remarks

(A15)

Price € 9950



KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Configuration 6x2
Gross vehicle weight 26,000 kg
Total fuel capacity 300 litre
Chassis-height 112 cm
Diff. locks 1
Wheelbase 480 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color Multicolored

Drivetrain

Engine capacity 257 Kw (349 Hp)
Euro 3
Gearbox kind Manual
Number of Gears 16
Clutch Pedal ✓
Power steering ✓
ABS ✓
ASR ✓
PTO ✓

Superstructure

Pump ✓

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleytn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Hydraulics

Tyres/Wheels

Tyres

Tires and axles



Tire size: 385/65R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/80R22,5
air suspension
Disc brakes



Tire size: 315/80R22,5
Lift axle
air suspension
Disc brakes

Contact information



info@kleytn.com

Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements