

DAF XF 440 SPACECAB MANUAL



Itemno 301741
 Kind Tractor unit
 Specification
 Matriculation year 2015 / 09
 Mileage 1,034,712 km
Chassisnumber
 XLRTEH4100G076964

Technical condition 
Remarks

(A15)

Price € 13900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Own weight 8,337 kg
 Gross vehicle weight 18,000 kg
 Total fuel capacity 1,250 litre
 2nd fuel tank ✓
 Fifth wheel height 118 cm
 Diff. locks 1
 Wheelbase 380 cm
 Suspension type air suspension

Cabin

Cabin type Space Cab
 Cruise control ✓
 Tacho ✓
 Digital tachograph ✓
 Airconditioning ✓
 Parking heater ✓
 Color Multicolored

Drivetrain

Engine make Paccar
 Engine capacity 320 Kw (435 Hp)
 Euro 6
 Gearbox kind Manual
 Number of Gears 16
 Clutch Pedal ✓
 Power steering ✓
 ABS ✓
 ASR ✓

Contact information



info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/80R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●●	Good state
●●●●●	Reasonable state
●●●●●	Moderate state
●●●●●	Does not meet requirements