

KRONE SD24 ALCOA'S DISC BRAKES



Itemno 301866
Kind Semi-trailer
Specification Curtainsider
Matriculation year 2015 / 04
Mileage

Chassisnumber
WKESD000000660539

Technical condition

Remarks

(A15)

Price € 9900

KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 5,790 kg
Gross vehicle weight 36,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Aluminium rims ✓
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,015
Inner box length 1,360 cm
Inner box width 248 cm
Inner box height 277 cm
Netto height 268 cm
Sliding roof ✓

Axle

Axle make BPW

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5
air suspension
Disc brakes



2

Tire size: 385/65R22,5
air suspension
Disc brakes



3

Tire size: 385/65R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles, 1 light blue: Good state
- 3 blue circles, 2 light blue: Reasonable state
- 2 blue circles, 3 light blue: Moderate state
- 1 blue circle, 4 light blue: Does not meet requirements