

IVECO 120E25 EURO CARGO E6 AIRCO TAILLIFT



Itemno 302224
Kind Truck
Specification Closed box
Matriculation year 2015 / 01
Mileage 418,400 km

Chassisnumber
ZCFA61EJ502621922

Technical condition

Remarks

(A15)

Price € 16950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 8,460 kg
Gross vehicle weight 12,000 kg
Total fuel capacity 300 litre
Diff. locks 1
Wheelbase 520 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color white

Drivetrain

Engine make Iveco
Engine capacity 185 Kw (251 Hp)
Euro 6
Gearbox kind AS-tronic
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 787 cm
Inner box width 246 cm
Inner box height 251 cm
Load bed height 99 cm
Netto height 239 cm

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 2,000 kg
Tail-lift make B.A.R cargolift
Tail-lift material aluminium
Tail-lift size 251 x 254

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Superstructure

Internal condition	●●●●●●●●
External condition	●●●●●●●●

Taillift

Controls	●●●●●●●●
System	●●●●●●●●

Tyres/Wheels

Tyres



1



Tire size: 265/70R19,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 265/70R19,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements