

SCANIA P400 8X4 HIAB 288 EP-5



Itemno 302274
Kind Truck
Specification Open with sideboards
Matriculation year 2011 / 07
Mileage 438,000 km

Chassisnumber
VLUP8X40009158142

Technical condition

Remarks
HIAB288EP-5 remote
(A15)

Price € 51900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	4
Configuration	8x4
Own weight	18,790 kg
Gross vehicle weight	32,000 kg
Total fuel capacity	300 litre
Diff. locks	2
Wheelbase	570 cm
Suspension type	spring suspension

Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Color	white

Drivetrain

Engine make	Scania
Engine capacity	294 Kw (400 Hp)
Euro	5
Gearbox kind	Manual
Number of Gears	12
Clutch Pedal	✓
Power steering	✓
ABS	✓
PTO	✓

Superstructure

Inner box length	720 cm
Inner box width	248 cm
Inner box height	74 cm
Load bed height	138 cm
Pump	✓

Crane

Crane	✓
Crane make	Hiab 288EP - 5
Year crane	2,011
Capacity crane	28
Maximum load	1400 Kg bij 15 M
Number of supports	4
CE-approved	✓
Control position	side control right
Remote control	✓
Crane position	Rear position
Hydraulic extendable	5 times
Extra hydr. conn.	4
Rotator	✓
Pallet-hook	✓

Remarks

Remarks	HIAB288EP-5 remote
---------	--------------------

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Hydraulics

Internal condition

External condition

Crane

Remote control

Supports

Mechanical

Hydraulics

Electrical

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 0/13R22,5
spring suspension
Drum brakes
Steering-axle, Mechanical



2
Tire size: 0/13R22,5
spring suspension
Drum brakes
Steering-axle, Mechanical



3
Tire size: 0/13R22,5
spring suspension
Hub-reduction
Drum brakes



4
Tire size: 0/13R22,5
spring suspension
Hub-reduction
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements