

SCHMITZ SKO 24 CARRIER VECTOR 1350



Itemno 303066
Kind Semi-trailer
Specification Frigo
Matriculation year 2014 / 12
Mileage

Chassisnumber
WSM00000005136090

Technical condition

Remarks

(A15)

Price € 15900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 10,015 kg
Gross vehicle weight 39,000 kg
Chassis type Incomplete chassis
Chassis material steel
Kingpin size 2 inch
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,014
Inner box length 1,340 cm
Inner box width 250 cm
Inner box height 265 cm
Netto height 264 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit vector1350
Enginetype frigo-unit fuel and electrical
Working hours electric 10
Working hours diesel 2,150
Wall thickness 40 mm

Axle

Axle make SCHMITZ

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 385/65R22,5

Lift axle

air suspension

Disc brakes



2

Tire size: 385/65R22,5

air suspension

Disc brakes



3

Tire size: 385/65R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements