

VOLVO FM 13.400 8X2 KENNIS CRANE



Itemno 303882
Kind Truck
Specification Open with sideboards
Matriculation year 2007 / 09
Mileage 748,811 km

Chassisnumber
YV2JSG0F07A647827

Technical condition

Remarks

(A15)

Price € 29950



KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 4
Configuration 8x2
Loading Capacity 23,810 kg
Own weight 13,190 kg
Gross vehicle weight 37,000 kg
Total fuel capacity 400 litre
Diff. locks 1
Wheelbase 510 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color Multicolored

Drivetrain

Engine make Volvo
Engine capacity 294 Kw (400 Hp)
Fuel type diesel
Euro 5
Gearbox kind I-Shift
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 680 cm
Inner box width 249 cm
Inner box height 100 cm
Load bed height 146 cm

Chairs

Number of seats 2

Crane

Crane ✓
Crane make Kennis R-16/7.10
Capacity crane 16
Maximum load 2550 Kg bij 5.9 m
Number of supports 2
CE-approved ✓
Crane position Movable
Hydraulic extendable 3 times
Extra hydr. conn. none
Rotator ✓
Pallet-hook ✓
Hook ✓

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Crane

Supports



Mechanical



Hydraulics



Electrical



Tyres/Wheels

Tyres



Tires and axles

1



Tire size: 385/65R22,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 385/65R22,5

spring suspension

Disc brakes

Steering-axle, Mechanical

3



Tire size: 315/80R22,5

air suspension

Disc brakes

4



Tire size: 385/65R22,5

Lift axle

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

