

DAF XF 440 SPACECAB MANUAL



Itemno 304105
Kind Tractor unit
Specification
Matriculation year 2014 / 09
Mileage 962,348 km

Chassisnumber
XLRTEH4100G039904

Technical condition 

Remarks

(A15)

Price € 17900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	7,866 kg
Gross vehicle weight	19,500 kg
Total fuel capacity	850 litre
Fifth wheel height	114 cm
Diff. locks	1
Wheelbase	380 cm
Suspension type	air suspension

Cabin

Cabin type	Space Cab
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Multicolored

Drivetrain

Engine make	Paccar
Engine capacity	320 Kw (435 Hp)
Euro	6
Gearbox kind	Manual
Number of Gears	16
Clutch Pedal	✓
Power steering	✓
ABS	✓
ASR	✓
PTO	✓

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



Tire size: 315/80R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/80R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements