

MERCEDES-BENZ ACTROS 1843 LS STREAMSPACE



Itemno 304128
Kind Tractor unit
Specification
Matriculation year 2016 / 05
Mileage 906,181 km

Chassisnumber
WDB96340310054011

Technical condition

Remarks

(A15)

Price € 15900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	8,132 kg
Gross vehicle weight	19,000 kg
Total fuel capacity	1,300 litre
2nd fuel tank	✓
Fifth wheel height	119 cm
Diff. locks	1
Wheelbase	380 cm
Suspension type	air suspension

Cabin

Cabin type	Sleeping cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Multicolored

Drivetrain

Engine capacity	315 Kw (428 Hp)
Euro	6
Gearbox kind	Telligent
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/80R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements