

M.A.N. 8.150 L2000 TIPPER BOX NL-TRUCK



Itemno 304159
Kind Tipper
Specification
Matriculation year 1993 / 11
Mileage 245,307 km

Chassisnumber
WMAL200652G087615

Technical condition

Remarks

(A15)

Price € 6950



KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 2,990 kg
Own weight 4,500 kg
Gross vehicle weight 7,490 kg
Total fuel capacity 100 litre
Wheelbase 426 cm
Suspension type spring suspension

Cabin

Cabin type Short cabin
Tacho ✓
Color Yellow

Drivetrain

Engine capacity 118 Kw (160 Hp)
Fuel type diesel
Euro 1
Gearbox kind Manual
Number of Gears 5
Clutch Pedal ✓
Power steering ✓
ABS ✓
PTO ✓

Superstructure

Inner box length 503 cm
Inner box width 226 cm
Inner box height 181 cm
Load bed height 109 cm
Netto height 181 cm
Pump ✓

Tyres/Wheels

Sparewheel ✓
Spare tire profile 2 mm

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Hydraulics

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 215/75R17,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 215/75R17,5
spring suspension
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements