VOLVO FH 13.480 6X4



Itemno Kind Specification Matriculation year Mileage Chassisnumber YV2ASW0D69A678849

304461 Truck Chassis Cabin 2009 / 06 1,363,930 km

Kleyn Trucks B.V.® PO Box 3 4214 ZJ Vuren Industrieweg 2 4214 KZ Vuren The Netherlands

IBAN: NL91RABO0103247157 SWIFT/BIC: RABONL2U

KvK 11013784 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3 Configuration 6x4 Loading Capacity 11,210 kg 16,790 kg Own weight 28,000 kg Gross vehicle weight Total fuel capacity 850 litre Trailer coupling Unbraked towing capacity 750 kg Braked towing capacity, center 24,000 kg axle Diff. locks 2 Wheelbase 460 cm Suspension type air suspension

Cabin

Cabin type Cruise control Tacho Digital tachograph Airconditioning Parking Airco Parking heater Color Reversing camera

Drivetrain

Engine make	Volvo
Engine capacity	353 Kw (480 Hp)
Fuel type	diesel
Euro	5
Gearbox kind	I-Shift
Number of Gears	12
Power steering	
ABS	
ASR	

Chairs

Number of seats

Contact information



info@kleyn.com Tel: +31 183 668 222

2

Sleeping cabin


Multicolored

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Tacho	
Dashboard display codes	
Electrical	
Cabin	
Internal	000
External	000
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Drivetrain Engine, general	
Engine, general	
Engine, general Cooling system	
Engine, general Cooling system Fuel system	
Engine, general Cooling system Fuel system Exhaust system	
Engine, general Cooling system Fuel system Exhaust system Greasing system	
Engine, general Cooling system Fuel system Exhaust system Greasing system Gearbox	
Engine, general Cooling system Fuel system Exhaust system Greasing system Gearbox Clutch	

TRUCKS

Kleyn Trucks B.V.® PO Box 3 4214 ZJ Vuren Industrieweg 2 4214 KZ Vuren The Netherlands

IBAN: NL91RABO0103247157 SWIFT/BIC: RABONL2U

KvK 11013784 BTW/VAT NL004676841B01

Tires and axles



Contact information



info@kleyn.com Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
00000	Reasonable state
	Moderate state
00000	Does not meet requirements