


HERTOGHS O3 45FT HIGH CUBE MEGA



Itemno 304546
Kind Semi-trailer
Specification Container transport
Matriculation year 2014 / 01
Mileage
Chassisnumber XL90Z339SEC196412
Technical condition 
Remarks

(A15)

Price € 4900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Loading Capacity 34,060 kg
Own weight 4,940 kg
Gross vehicle weight 39,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Wheelbase 884 cm
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,014
Load bed height 105 cm
Container sizes 1X45 high cube

Axle

Axle make SAF

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 435/50R22,5
air suspension
Drum brakes



2

Tire size: 435/50R22,5
air suspension
Drum brakes



3

Tire size: 435/50R22,5
air suspension
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements