

KRONE SD



Itemno 304572
Kind Semi-trailer
Specification Container transport
Matriculation year 2011 / 09
Mileage
Chassisnumber
WKESD000000509376
Technical condition 
Remarks

(A15)

Price € 4900

KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 5,900 kg
Gross vehicle weight 41,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,011
Twistlocks 2x20 + 1x30 + 1x40 + 1x45 high cube

Lowloader

Extendable chassis Front / Rear / Top

Axle

Axle make BPW

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/55R22,5

Lift axle

air suspension

Disc brakes



2

Tire size: 385/55R22,5

air suspension

Disc brakes



3

Tire size: 385/55R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles: Good state
- 3 blue circles: Reasonable state
- 2 blue circles: Moderate state
- 1 blue circle: Does not meet requirements