

RENAULT C 430 HIAB 188ES5



Itemno 304752
Kind Truck
Specification Platform
Matriculation year 2016 / 06
Mileage 314,208 km

Chassisnumber
VF630N16XGD000791

Technical condition

Remarks
HIAB 188ES5
(A15)

Price € 59900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x4
Own weight	15,255 kg
Gross vehicle weight	29,000 kg
Total fuel capacity	350 litre
Trailer coupling	✓
Diff. locks	2
Wheelbase	460 cm
Suspension type	spring suspension

Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Color	Red
Reversing camera	✓

Drivetrain

Engine make	Renault
Engine capacity	316 Kw (429 Hp)
Euro	6
Gearbox kind	Optidriver
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓
PTO	✓

Superstructure

Inner box length	622 cm
Inner box width	242 cm
Load bed heigh	140 cm
Pump	✓

Crane

Crane	✓
Crane make	Hiab X - HIDUO 188
Year crane	2,016
Capacity crane	18
Maximum load	?
Number of supports	2
CE-approved	✓
Control position	side control right
Remote control	✓
Crane position	Rear position
Hydraulic extendable	5 times
Extra hydr. conn.	4
Pallet-hook	✓

Remarks

Remarks	HIAB 188ES5
---------	-------------

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Superstructure

Hydraulics	●●●●●●●●
Internal condition	●●●●●●●●
External condition	●●●●●●●●

Crane

Remote control	●●●●●●●●
Supports	●●●●●●●●
Mechanical	●●●●●●●●
Hydraulics	●●●●●●●●
Electrical	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



1
Tire size: 0/13R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



2
Tire size: 0/13R22,5
spring suspension
Disc brakes



3
Tire size: 0/13R22,5
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements