

SCANIA P410 6X2 RETARDER 2T LIFT



Itemno 304853
Kind Truck
Specification Closed box
Matriculation year 2019 / 11
Mileage 309,836 km

Chassisnumber
YS2P6X20005571529

Technical condition

Remarks

(A15)

Price € 72950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Configuration 6x2
Own weight 11,510 kg
Gross vehicle weight 26,500 kg
Total fuel capacity 500 litre
Trailer coupling ✓
Kingpin size 40 DIN
Diff. locks 1
Wheelbase 495 cm
Suspension type full air suspension

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 2,000 kg
Tail-lift make BAR Cargolift
Tail-lift material aluminium
Tail-lift size 195x252

Tyres/Wheels

Sparewheel ✓
Spare tire profile 13 mm

Cabin

Cabin type Sleeping cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Parking Airco ✓
Parking heater ✓
Color white

Drivetrain

Engine capacity 301 Kw (409 Hp)
Euro 6
Gearbox kind Opti-cruise
Number of Gears 12
Add. break system ✓
Retarder make Scania
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 730 cm
Inner box width 248 cm
Inner box height 269 cm
Load bed height 125 cm
Netto height 264 cm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 315/70R22,5

air suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/70R22,5

air suspension

Disc brakes

3



Tire size: 315/70R22,5

Lift axle

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements