

DAF CF 480 FAD 8X4 HYVA 26.57SK



Itemno 304988
Kind Truck
Specification Hooklift
Matriculation year 2018 / 07
Mileage 175,647 km

Chassisnumber
XLRADM4300G204117

Technical condition

Remarks
HYVA 26.57 SK HOOKLIFT / FAD 8X4
(A15)



Price € 84950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	4
Configuration	8x4
Own weight	14,430 kg
Gross vehicle weight	32,000 kg
Total fuel capacity	325 litre
Diff. locks	2
Wheelbase	436 cm
Suspension type	spring suspension

Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Color	Black

Drivetrain

Engine capacity	355 Kw (482 Hp)
Euro	6
Gearbox kind	AS-tronic
Number of Gears	12
Power steering	✓
ABS	✓
PTO	✓

Superstructure

Material superstructure	steel
Inner box length	558 cm
Inner box width	234 cm
Inner box height	99 cm
Load bed height	140 cm
Systemlength	544 cm
Bulk capacity	13
Bulkcontent measure	m3
Pump	✓

Remarks

Remarks	HYVA 26.57 SK HOOKLIFT / FAD 8X4 FULL STEEL / LUXURY AIR LEATHER SEAT / INCL BOX.
---------	--

Contact information



info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Superstructure

Hydraulics	●●●●●
Internal condition	●●●●●
External condition	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



1
Tire size: 315/80R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



2
Tire size: 315/80R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



3
Tire size: 315/80R22,5
spring suspension
Hub-reduction
Drum brakes



4
Tire size: 315/80R22,5
spring suspension
Hub-reduction
Drum brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●●	Good state
●●●●●	Reasonable state
●●●●●	Moderate state
●●●●●	Does not meet requirements