

VOLVO FM 9.380 GLOBE NL-TRUCK



Itemno 305153
Kind Tractor unit
Specification
Matriculation year 2006 / 04
Mileage 1,518,951 km

Chassisnumber
YV2JH30A76B431400

Technical condition

Remarks
ANALOG TACHO
(A15)

Price € 8950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	12,020 kg
Own weight	6,580 kg
Gross vehicle weight	18,600 kg
Total fuel capacity	530 litre
Fifth wheel height	108 cm
Diff. locks	1
Wheelbase	380 cm
Suspension type	air suspension

Cabin

Cabin type	Sleeping cabin
Cruise control	✓
Tacho	✓
Airconditioning	✓
Color	white

Drivetrain

Engine capacity	279 Kw (379 Hp)
Fuel type	diesel
Euro	3
Gearbox kind	I-Shift
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Chairs

Number of seats	2
-----------------	---

Remarks

Remarks	ANALOG TACHO
---------	--------------

Contact information



info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 295/60R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●○	Good state
●●●○●	Reasonable state
●●○●●	Moderate state
●●○○●	Does not meet requirements