

MERCEDES-BENZ ATEGO 1524 Carrier Supra 850



Itemno 305277
Kind Truck
Specification Frigo
Matriculation year 2018 / 05
Mileage 249,465 km

Chassisnumber
WDB96702710248476

Technical condition

Remarks
Carrier Supra 850 D+E,1500 kg lift
(A15)

Price € 58900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 8,570 kg
Gross vehicle weight 15,000 kg
Total fuel capacity 125 litre
Wheelbase 540 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color white
Reversing camera ✓

Drivetrain

Engine make Mercedes
Engine capacity 176 Kw (239 Hp)
Euro 6
Gearbox kind Automatic
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Matr. year superstructure 2,018
Inner box length 828 cm
Inner box width 246 cm
Inner box height 214 cm
Load bed height 117 cm
Netto height 209 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit SUPRA 850
Enginetype frigo-unit fuel
Isolated box ✓
Wall thickness 55 mm
Type of cooling Cooling

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 1,500 kg
Tail-lift make Palfinger
Tail-lift material aluminium
Tail-lift size 220 x 255

Remarks

Remarks Carrier Supra 850 D+E,1500 kg lift

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Superstructure

Internal condition	●●●●●●●●
External condition	●●●●●●●●

Refrigeration unit

Systems	●●●●●●●●
---------	----------

Taillift

Controls	●●●●●●●●
System	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



1 Tire size: 285/70R19,5
spring suspension
Disc brakes



2 Tire size: 285/70R19,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements