

RENDERS RPS



Itemno 305543
 Kind Semi-trailer
 Specification Container transport
 Matriculation year 2005 / 02
 Mileage
Chassisnumber
 YA5B321N443B40002
 Technical condition
Remarks

(A15)

Price € 3950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
 Loading Capacity 37,500 kg
 Own weight 5,500 kg
 Gross vehicle weight 43,000 kg
 Chassis type Complete chassis
 Chassis material steel
 Kingpin size 2 inch
 Suspension type full air suspension

Cabin

Color Blue

Drivetrain

Engine capacity (0 Hp)
 ABS ✓
 EBS ✓

Superstructure

Matr. year superstructure 2,005
 Container sizes all connections

Lowloader

Extendable chassis Front / Middle / Rear

Axle

Axle make BPW

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5

Lift axle

air suspension

Drum brakes



2

Tire size: 385/65R22,5

air suspension

Drum brakes



3

Tire size: 385/65R22,5

air suspension

Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles, 1 light blue: Good state
- 3 blue circles, 2 light blue: Reasonable state
- 2 blue circles, 3 light blue: Moderate state
- 1 blue circle, 4 light blue: Does not meet requirements