

SCANIA G500 6X2/4 RETARDER PTO



Itemno 305687
Kind Tractor unit
Specification
Matriculation year 2020 / 07
Mileage 640,566 km

Chassisnumber
YS2G6X20005591193

Technical condition

Remarks

(A15)

Price € 48950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x2
Own weight	9,140 kg
Gross vehicle weight	26,500 kg
Total fuel capacity	540 litre
Fifth wheel height	119 cm
Diff. locks	1
Wheelbase	410 cm
Suspension type	air suspension

Cabin

Cabin type	Sleeping cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	white

Drivetrain

Engine capacity	368 Kw (500 Hp)
Euro	6
Gearbox kind	Opti-cruise
Number of Gears	12
Add. break system	✓
Retarder make	Scania
Power steering	✓
ABS	✓
ASR	✓
Hydraulic installation	✓
PTO	✓

Superstructure

Pump	✓
------	---

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Tyres/Wheels

Tyres

Tires and axles



Tire size: 385/65R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
Lift axle
air suspension
Disc brakes



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements