

SCHMITZ SKI 24-7.2 24 M3 ALU SAF DISC



Itemno 305974
Kind Semi-trailer
Specification Tipper
Matriculation year 2008 / 07
Mileage

Chassisnumber
WSK00000001244651

Technical condition

Remarks

(A15)

Price € 7450



KLEYN TRUCKS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP VANS TRAILERS SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 5,279 kg
Gross vehicle weight 33,000 kg
Chassis type Complete chassis
Chassis material aluminium
Kingpin size 2 inch
Aluminium rims ✓
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,008
Tipping possibilities 1 side
Inner box length 730 cm
Inner box width 245 cm
Inner box height 130 cm
Bulk capacity 24
Bulkcontent measure m3

Axle

Axle make SAF

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5

Lift axle

air suspension

Disc brakes



2

Tire size: 385/65R22,5

air suspension

Disc brakes



3

Tire size: 385/65R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements