

DAF XF 480 SSC ALCOA'S PTO+HYDR



Itemno 306038
 Kind Tractor unit
 Specification
 Matriculation year 2017 / 09
 Mileage 737,062 km
Chassisnumber
 XLRTEH4300G175214

Technical condition 
Remarks

(A15)

Price € 19900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Loading Capacity 11,047 kg
 Own weight 8,453 kg
 Gross vehicle weight 19,500 kg
 Total fuel capacity 950 litre
 Fifth wheel height 117 cm
 Diff. locks 1
 Wheelbase 380 cm
 Aluminium rims ✓
 Suspension type air suspension

Cabin

Cabin type Super Space Cab
 Cruise control ✓
 Tacho ✓
 Digital tachograph ✓
 Airconditioning ✓
 Parking Airco ✓
 Parking heater ✓
 Color Multicolored

Drivetrain

Engine capacity 353 Kw (480 Hp)
 Fuel type diesel
 Euro 6
 Gearbox kind AS-tronic
 Number of Gears 12
 Power steering ✓
 ABS ✓
 ASR ✓
 Hydraulic installation ✓
 PTO ✓

Superstructure

Pump ✓

Chairs

Number of seats 2

Contact information



info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	---

Tires and axles



Tire size: 385/65R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 295/80R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements